

Findings / actions from the 2024-2025 report.

Outdoor Gym:

Teen Shelter has corrosion and fixtures are loose or missing – Treat & repair.

Chest Press immobilised and has corrosion – Treat & Repair.

Exercise Bike has corrosion – Treat & Repair.

Cross Trainer excessive movement or noisy operation and corrosion – Dismantle to investigate replacing components as necessary. Treat and repair corrosion.

Chinning Bars 2 tier has corrosion – Treat and repair.

Skate Park:

Single Point Swing – Trip points on matting to be repaired. Chain links work replace.

Cableway – Chain links worn replace. Finger Guard worn replace (the finger guard has been replaced).

Skate Park – Concrete edges are in poor condition – Repair.

Matting below single point swing – Matting is separating repair.

Wear in Goal mouth–surface has holes in it – repair

Children's play area:

Play area top entrance gate – adjust gate / posts and fit new rubber buffer to ensure a spacing of 12mm both sides of the gate. Replace missing latch. Trip point identified at entrance – level out.

Mutliplay Toddler metal/plastic with tunnel – safety surface cracked repair.

Swing mixed 2 bay 1 basket junior – Some chain wear on lower links and connectors on the junior swings - monitor and replace before 40% wear.

Basket Swing – Remove chain covers to inspect, some wear to exposed links. Service Chains and replace if required Protective cover from rim joint removed - replace. Surface Shrinkage re-glue and fill gaps and joints as necessary.

Swing Toddler 2 bay surface shrinkage – re-glue and fill gaps as necessary.

Carousel roundabout – Surface is wearing – monitor for significant deterioration and rectify when necessary.

Rope swing – Rope has started to sag – monitor.

Multiplay climber – Delamination of wood repair. Shrinkage of safety surface – repair. Top right climbing grip loose – tighten. Top rope damaged – repair.

Play area entrance gates – This is being covered as gates quotes have been obtained.

Multi play toddler – bolt cap damaged replace – Sharon to order

Basket swing hard or sharp projections where rope has been subjected to heat – remove pointed and sharp projections.

Muti play climber – Climbing grip loose – tighten.

Laminate damaged – rub down and treat damaged edges.